



**Roof painting, marble capitals netted, Spring 2010**

## **The Rotunda at UVA**



**Various Conditions at Sheet Metal Roof**

## **Rotunda Roof Replacement**



**Sheet metal rusting from below**



**Rotting wooden nailers**

## **Conditions Beneath Rotunda Roof**




**Erosion seen from below**



**Pieces of capitals removed for security**

## **Marble Capital Replacement**



Column capital on the South Portico showing typical conditions. Note several missing acanthus leaves


## Marble Capital Replacement



**Badly damaged brick at southeast corner**



**Moss, red mold and stains on marble**



**Open joints, stains and damage from salts on northeast corner**

## **Marble and Brick Repairs**